

L Number	Hits	Search Text	DB	Time stamp
1	1	de-3627463-\$.did.	DERWENT	2004/10/22 13:00
2	0	ep-0242783-\$.did.	DERWENT	2004/10/22 13:00
3	1	ep-242783-\$.did.	DERWENT	2004/10/22 13:08
4	1	ep-978589-\$.did.	DERWENT	2004/10/22 13:08
5	1	ep-502237-\$.did.	DERWENT	2004/10/22 13:48
6	26	ueberschar-manfred\$.in.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/22 13:52
7	33	henninger-christoph\$.in.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/22 13:52
8	16	wozny-eckard\$.in.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/22 13:52
10	258374	coating and (roll?\$2 or cylinder)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/22 13:53
11	245489	((force or pressure or pressing) near3 (sensor or detector or detecting or gage or gauge)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/22 13:56
12	8226	((coating and (roll?\$2 or cylinder)) and ((force or pressure or pressing) near3 (sensor or detector or detecting or gage or gauge))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/22 13:57
13	151	((coating and (roll?\$2 or cylinder)) and ((force or pressure or pressing) near3 (sensor or detector or detecting or gage or gauge))) and (strain near gauge)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/22 13:57
14	516	((coating and (roll?\$2 or cylinder)) and ((force or pressure or pressing) near3 (sensor or detector or detecting or gage or gauge))) and (strain near gauge)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/22 13:57
15	488	((coating and (roll?\$2 or cylinder)) and ((force or pressure or pressing) near3 (sensor or detector or detecting or gage or gauge))) and (strain near gauge) not (((coating and (roll?\$2 or cylinder)) and ((force or pressure or pressing) near3 (sensor or detector or detecting or gage or gauge))) and (strain near gauge))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/22 13:57